

LUCIDE

INSTALLATION DRAWING SPECIFICATIONS

| | | | | | |
|--|--|------------------------------|---------------------------------|--|--|
| <p>1.</p> <ul style="list-style-type: none"> x4 x4 x1 x1 x1 | <p>2.</p> | | | | |
| <p>3.</p> <p>70mm</p> <p>200mm</p> <p>H07 RN-F</p> <p>H05 RN-F</p> | <p>4.</p> <p>DIP SWITCH</p> <p>working light sens time-delay adjust</p> <p>ON OFF</p> <p>The above shows the factory settings, if need, please reset it according to the left drawing.</p> | | | | |
| <p>5.</p> | <p>6.</p> | | | | |
| <p>1.5-3m</p> <p>4m</p> <p>8m</p> | <table border="1"> <tr> <td data-bbox="791 1659 1002 1861"> <p>0-8m</p> <p>Detection</p> </td> <td data-bbox="1034 1659 1254 1861"> <p>100°</p> <p>Sensor range</p> </td> </tr> <tr> <td data-bbox="791 1883 1002 2085"> <p>Twilight setting</p> <p>10-2000 LUX</p> </td> <td data-bbox="1034 1883 1254 2085"> <p>Time setting</p> <p>5 sec-8 min</p> </td> </tr> </table> | <p>0-8m</p> <p>Detection</p> | <p>100°</p> <p>Sensor range</p> | <p>Twilight setting</p> <p>10-2000 LUX</p> | <p>Time setting</p> <p>5 sec-8 min</p> |
| <p>0-8m</p> <p>Detection</p> | <p>100°</p> <p>Sensor range</p> | | | | |
| <p>Twilight setting</p> <p>10-2000 LUX</p> | <p>Time setting</p> <p>5 sec-8 min</p> | | | | |